

Door T - Hinged Kalamein Passage to Office

3 Butts BB-180 - $4\frac{1}{2}$ x $4\frac{1}{2}$

Lock 324 $\frac{1}{2}$

Scope:- 1. Pull 07935 Stations are intended to cover the
Push Plate Cast Brass Oval $3\frac{1}{2}$ x 16

furnishing of all labor and materials required to clean,

Cleaning:- and paint all wooden, metal and masonry

surfaces. All surfaces and glazing in same to be turned

over clean and in first class condition.

General:- No outside painting is to be done during wet or
freezing weather.

No paint is to be applied until preceding coat has
become thoroughly dry.

All materials to be the best of their respective
kinds and to be delivered to the building in manufacturer's
unbroken containers, with analysis on each can.

Where manufacturers' names and number are given,
they are indicative of the quality and composition of
paint. Other well recognized paints having same composi-
tion will be considered.

All colors to differ from the preceding coat.

Structural Steel:- Thoroughly clean all surfaces, removing
all dirt, rust, oil, grease, scale and other foreign materials,
leaving the clean metal exposed ready to receive the paint.

All surfaces inaccessible after assembly to be
painted before assembly.

Shop coat to be dry before shipment.

All surfaces inaccessible after erection to be pain-
ted first field coat before erection.

Second field coat not to be applied until after e-